



Electrical Industry
Health & Safety Group

Shared Learning

Working at Height



Self rescue from height

What happened?

At approximately 50-metre height, two technicians were working on a turbine blade repair when the crane had suddenly stopped. The crane operator informed the technicians he could not fix the fault himself and required assistance - stranding the two technicians.

The technicians descended from height using the RESQ- Rescue Kit.

Wind Assets

What did we learn?

With previous training the technicians were able to keep a clear head during an emergency.

The technicians had plenty of time talk through their options, arrange the RESQ Rescue Kit for the best set-up that suited themselves and rehearse the descent before exiting the man basket.

